


PART #


PCS75/USB

310.318.2491 • 800.523.1269 • www.mockett.com




NOTE:

- 6 ft. cord length.
- USB ports are for charging use only.
- For use on a normally dry work surface.
- Table thickness is 5/16" MIN. to 1-7/16" MAX.
- Power adapter dimension is 3-3/8" X 1-29/32" X 1-1/2".




TOP VIEW




FRONT VIEW

1



Determine the position and location of the unit in the work surface and make the cut out. Allow enough clearance for unit operation. DO NOT place unit where cable is strained or trapped.

2



Install the PCS75/USB grommet into the cut out and make sure it is fully leveled onto the work surface.


TABLE OF CONTENTS:



..... 1X USB insert



..... 1X PCS75/USB Grommet




..... 1X Power adapter




..... 1X Lock ring

3




Tighten the lock ring until the grommet is secure.

4




Guide the power adapter cord through the bottom of the grommet.

5



Plug the power adapter connector into the USB insert.

6



Align and install the USB insert into the open slot on the grommet. Plug power adapter into a nearby outlet and the unit is ready for use.