






1




Determine the mounting position and location of the part in the work surface. Mark the mounting positions and install one end of the end cap in the work surface. (Note: Mounting hardware not included.)

2





Slide the hooks into the track.

3



Place one end of the loaded track into the installed end cap slot. Align and mount the other end cap. Secure the part with the mounting hardware.

TABLE OF CONTENTS:

	2 X WM27 End Cap
	1 X WM27 Track
	15 X WM27 Hook