





NOTE:


- Maximum cord diameter is 5/8".

2a Magnetic metal surfaces




Determine the position and location of the part on the magnetic metallic work surface. Affix the part to the desired work surface. See Step 2b for optional WM44 Steel Plate.

3b




Place the WM44 Steel Plate on the desired work surface and then affix the part on the WM44 Steel Plate.

1



Unsnap and place the wires in the WM44. Snap close when finished.

2b Non-Magnetic/Non-Metallic surfaces



Determine the position and location of the part on the non-magnetic/non-metallic work surface. Peel adhesive backing from the WM44 Steel Plate.

TABLE OF CONTENTS:



.....1X WM44



.....1X WM44 Steel Plate