KEILHAUER

Tool Required

5/32"" Hex Allen Key

Phillips head screw driver

Hardware Included

1/4-20 x 2"
Flat head cap screw
(x8)

#6-32 x 3/4"
Rounded head screw
(x8)

1/4-20 x 5/8"
Button head cap screw
(x6)

Glide
(x4)

Forsi Table
Assembly Instructions

1

Place the table top upside down on a blanket.

2

Installed

Using the 5/32" hex key, fasten the steel frame with 1/4"-20 x 5/8" button head cap screw (x6).

3

Install the table leg (x2) onto the table top and the steel frame at the four mount locations. Using the 5/32" hex key fasten with 1/4"-20 x 2" flat head cap screw (x8).

4

Using the Phillips head screw driver, install the glide (x4) using #6-32 x 3/4" rounded head screw (x8).

5

Place assembled table in its final position.

KEILHAUER

Tool Required

Phillips head screw driver

Hardware Included

#8-15 x 1/2"
Quad head wood screw
(x1)

Power Unit
(x1)

Cable Clamp
(x1)

Cable Mangement
Track
(x1)

Forsi Power Table
## Assembly Instructions

1

Install the power unit (x1) through the hole cut out of the table top. See supplied power unit installation instructions.

2

Underside of table shown.

Remove the adhesive backing from the cable management track (x1) and press onto the center inside table leg. Feed the power cable into the cable management track.

3

Underside of table shown.

Using the Phillips head screw driver install the cable clamp (x1) with the #8-15 X 1/2" quad head wood screw.

4

Place the assembled table in it's final position.

keilhauer.com