ACCREDITED
TESTING CERT. #3193.01

553 76th Street · Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 53771 Date: 08-14-2012

For the Account Of:

Pollack

150 Varick Street

New York, NY 10013

Contact:

Lawrence Hoysic

Client's Identification:

Dottie 2370

Test Performed

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 – CS 191-53) Upholstery Fabrics, March 2000

TEST DATA

☐ Plain Surface

□ Raised Surface

Flame Spread Warp Face	Flame Spread Warp Back
(seconds)	(seconds)
DNI	
DNI	
DNI	
	DNI
	DNI
	Warp Face (seconds) DNI DNI

	Flame Spread	Flame Spread
	Fill Face	Fill Back
Specimen	(seconds)	(seconds)
1	DNI	
2	DNI	
3	DNI	
4		DNI
5		DNI

ABBREVIATIONS USED

DNI Did not ignite when exposed to test ignition source

IBE Ignited but extinguished before burning through stop cord

SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric TSF Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds. (ACT Criteria decreases minimum time to 4 seconds)
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION Based on the above Results and Acceptance Criteria, the item tested:

☐ Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature-MB