

IMPORTANT!
READ FIRST IF ROTATING REFLECTOR!

SUPPLEMENTAL INSTRUCTIONS – TYPE “FR” HILTON SERIES

WARNING: Failure to properly route socket wire harness may result in damage to harness.

DO NOT ROUTE HARNESS OVER TOP OF REFLECTOR.

This reflector can be rotated to 3 positions for optimum light direction. This also places the ballast in 1 of 3 positions in relation to reflector. You must re-route wiring if rotating reflector from fixture's as-shipped position. Match ballast location in relation to reflector using below figures. Star represents ballast, arrows point to loops.

FIGURE 1 Route harness through side loop again.





FIGURE 2 Route harness through opposite side loop.



LSI INDUSTRIES INC.
10000 Alliance Road ♦ Cincinnati, Ohio 45242 ♦ (513) 793-3200 ♦ Fax (513) 984-1335 ♦ www.lsi-industries.com