



# INSTALLATION OF GLARE SHIELD HILTON® II SERIES — ARM MOUNT

1. Position shield on fixture as shown in Figure 2 and mark drilling locations through holes in shield (see Figure 1).
2. Remove shield and drill ½" dia. holes through housing (4 places).
3. Insert well-nut into each hole.
4. Position and install glare shield using ¼-20 screws and flat/lock washers.
5. Tighten screws until snug.




**NOTE:** Glare shield should be placed on side that will best block light from the area to be shielded, and that will allow maximum reflector performance (see Figure 3).

**FIGURE 2: SHIELD POSITIONING**



**FIGURE 3**

Drawings below show location of shields for best performance of reflector. Whenever possible, glare shields should be placed in the indicated positions. (See shaded areas.)



LSI LIGHTING SYSTEMS  
An LSI Industries Company  
10000 Alliance Road  
Cincinnati, Ohio 45242  
(513) 793-3200 Fax (513) 984-1335  
www.lsi-industries.com