INSTALLATION AND ASSEMBLY INSTRUCTIONS Sterling XSB Series HSS HOUSE SIDE SHIELD



WARNING: Failure to follow instructions could result in damage

to product and void warranties!


WARNING: Risk of fire or electrical shock. Disconnect power before installing or servicing.

WARNING: Before proceeding, read all instructions carefully to ensure proper and safe installation.

IMPORTANT: This product must be installed in accordance with the applicable installation code by a person familiar with the construction and operation of the product and the hazards involved.

Tools required: Drill & 11/64" drill bit, and size T20 Torx driver.

1. Shield can be mounted on any side of Luminaire.










XSB HSS, cont'd.

2. After determining which side to mount Shield to, locate (4) dimples in Luminaire that require drilling.



- 3. Drill (4) dimples to a MAXIMUM depth of 1/4" deep. DO NOT EXCEED 1/4" DEPTH!
- 4. Position Shield to Luminaire. Secure Shield to Luminaire using (4) supplied screws. Tighten (4) screws evenly.



Installation Questions?
Call LSI Field Service Department at:
1-800-436-7800 Ext. 3300
Fax: 1-877-861-1368

2/2

(513) 793-3200

nerican Innovation Through Technology

LSI Industries Inc. 10000 Alliance Road Cincinnati, Ohio 45242

Fax (513) 793-0147 www.lsi-industries.com

p/n 530308 Rev. 4/13

LSI Industries Inc. 10000 Alliance Road Cincinnati, Ohio 45242 (513) 793-3200 Fax (513) 793-0147 www.lsi-industries.com

530308 Rev. 4/13 ©2013 LSI Industries Inc.