



Laredo

A great feeling leather that is meant to show all the natural marks and defects one would expect from a leather after much wear and tear. You'll find scratches, uneven color, pebbling, and something even an artist would have difficulty making. It's all done by hand and it's beautiful.

Specifications

Average Hide Size: 50 Square Feet

Configuration: Whole Hide

Hide Source: Brazil


Thickness: 1.0-1.2 mm

Finish: Aniline

Resistance to Scratching: High Resistance

Flammability: NFPA 260 Pass, CAL 117 Pass

Anti-Soil Treatment: Available For This Article



Care and Cleaning

Leather is a natural material and, if properly cared for, will maintain its beauty and usefulness for many years. Direct exposure to strong light can cause any leather color to fade, so always protect leather from direct sunlight and other intense light sources. It is also advised that leather products be kept away from radiators or other generators of heat. Periodic dusting and vacuuming is recommended for normal maintenance of leather. Should leather get marked or stained, please use only mild soap and water and first test a discrete area before treating the affected spot. Do not use Saddle Soap, cleaning solvents, oil, or abrasive cleaners.

** For Suede, Transfer, Hair on Hide and Customized non-standard leather – please contact the Demar Leather main office for additional information