

MM3/SET


PROPRIETARY AND CONFIDENTIAL.

ALL DIMENSIONS HAVE A $\pm 1/32"$ TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

SPECIFICATIONS

- Maximum cord diameter is $5/8"$.


TABLE OF CONTENTS




..... 1X MM3A



..... 1X MM3




TOP VIEW




FRONT VIEW

1



Make a cut out in the desired location on your work surface.
Cut a hole at $1-7/8"$ diameter.

2




Install the MM3A into the cut out and make sure it is fully leveled onto the work surface.

MM3/SET

PROPRIETARY AND CONFIDENTIAL.

ALL DIMENSIONS HAVE A $\pm 1/32"$ TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

3



Insert MM3 into the MM3A.