


Parts Diagram

Torsion Air® Stack Chair
Sled Base Armchair

September 2019



.XX = Select Color

TARF includes Items 5, 18, 19 and choice of glide.

Item 12 requires Item 13 and attaches using Item 17.

Item 14 requires Item 16 for attachment.

Item 15 requires Item 17 for attachment.

TARC is ordered with or without shroud. With shroud includes Items 3 & 4. Without shroud is just TARC.

Item	Part Number	Item Description	Req Qty
1	46.3333.XXMH.X	Assembly, Mesh Backrest	1
2	TARC	Seat Cushion, Upholstered (see note)	1
3	46.3346.BL.X	Shroud, Stacking Chair Seat	1
4	12.0055.CZ.X	Screw, #10-16 x 1/2" PTH Type AB T/F BLK ZC	5
5	PT.06.7012.BL.X	Cap, Back Support	2
6	TARF	Replacement Frame, Torsion Air (see note)	1
7	12.9011.X	Cap Screw, M5 x 30 CLS 10.9 FSHCS PIn	4
8	46.3338.R.BL.X	Arm Cap, Right	1
9	46.3338.L.BL.X	Arm Cap, Left	1
10	12.0696.TR.X	Screw, #8 x 5/8" TX OV HD T-B Blk OX	2
11	12.0011.X	Screw, M6 x 18 PPH "BosScrew"	4
12	PT.06.6033.X	Glide, Stainless Steel Plastic Housing (GSS) (see note)	4
13	PT.06.6034.X	Steel Insert, Stainless Steel Glide (GSS) (see note)	4
14	PT.06.6032.BL.X	Glide, Black Plastic (GBL) (see note)	4
	PT.06.6032.N.X	Glide, Non-Marring Plastic (GNM) (see note)	4
15	10.0128.X	Glide, Non-Skid (Dual Durometer) (GNS) (see note)	4
16	12.4016.X	Screw, #8 x 1/2" PPH Type 25 T/C ZC (GBL & GNM)	4
17	PC.12.0583.X	Screw, #8 x 1/2" PPFH Type-B T/SZC (GNS & GSS)	4
18	PT.06.6031.XXX	Bumper, Stacking	2
19	PT.12.0583.X	Screw, #8 x 1/2" PFH Type B	2

