

Gulfport #R3032

Product Specification

Face Construction	Imperial	Metric
Construction	Multicolor Level Cut Loop	
Tufted Pile Weight	26 oz/sq yd	881 g/sq m
Twist Level	4.91 TPI	
Gauge	1/10 inch	39.4 rows/10 cm
Stitches per Inch	9 stitches / inch	35.4 stitches/10 cm
Pile Height	0.312 inch Cut	7.9 mm
	0.250 inch Loop	6.4 mm
Total Weight	62.0 oz/sq yd	2102 g/sq m
Pile Density	3000	
Fiber System	100% Solution-dyed Primus® PET	Fiber
Dye Method	Solution Dyed	
Pattern Repeat	12" W x 15" L	304 mm W x 381 mm L
Primary Backing	Woven Polypropylene	
Backing Construction	Actionbac®	
Width	12 feet	366 cm

Product Testing/Information

Surface Flammability	Flooring Radiant Panel	ASTM E-648 Class 1	
	Smoke Density	ASTM E-662 Less than 450	

The product, represented by averages of testing from random samplings of production lots, meets or exceeds the above Test Results.

Installation and Maintenance

Carpet should be installed in accordance with the Carpet and Rug Institute's standard CRI-104. Carpet must be over manufacturer's recommended pad.

Stretch-In Installation: Establish roll sequencing, dry lay carpet, and apply latex seam sealer to both edges. Pre-stretch the sections with shorter pattern measurements to align with longer patterns in order to make hot melt seam (use 6" tape to prevent seam peaking). A two-headed power stretcher or "deadman" must be used to achieve this. Once the seam is made, proceed with proper stretch installation (CRI-104, figure "Stretch Diagram"). The use of architectural or double tackless strip is required to be used throughout a

Pattern streaks and banding are visually apparent streaking in patterned carpet resulting from linear juxtaposition of pattern elements visible in both length and width direction. IT IS NOT A CARPET DEFECT, but is inherent in solution dyed graphic and cut/loop patterns.

Warranties

Limited 10 Year Abrasive Wear Warranty Limited 10 Year Manufacturing Warranty

Product Notes

- 1. All specifications are subject to normal manufacturing tolerances.
- 2. Dyelots may vary from samples.
- 3. The use of chair pads under roller caster chairs is required in order to maintain full limited warranty coverage.
- 4. Tarkett reserves the right to change specifications and construction materials without notice due to raw material shortages or technological improvements, contact your representative for confirmation.

Tarkett North America

Technical Services Department 285 Kraft Drive Dalton, GA 30721 USA: 800-871-3211