

wright · line **Vertical Power**  
technical environment solutions **Mounting Brackets**

## VERTICAL POWER MOUNTING BRACKETS

### PART INVENTORY – 4PRPWRBRKT VERTICAL POWER MOUNTING BRACKETS


- (2) Power Brackets
- (2) 1/4-20 x 1/2" Allen Head Cap Screws
- (1) 5/32" Allen Wrench

### TOOL REQUIRED

- (1) 5/32" Allen Wrench (*Supplied with 4PRPWRBRKT*)

#### 1. Determine Bracket Positions:

Note: There are two positions at the top and the bottom of the rack for the Vertical Power Mounting Brackets. Refer to figure 1 to determine the appropriate bracket position for your power strip.



Power Option	Bracket Position	Mounting Distance
Wright Line Vertical PDU	Positions 1&4	67.25"
Wright Line Vertical Slimline	Positions 2&3	52.25"
3rd Party PDU (teardrop mount)	Positions 1&3	61.25"

Figure 1

wright-line **Vertical Power  
Mounting Brackets**  
technical environment solutions

2. Assemble the Vertical Power Brackets:




Figure 2

3. Attach the power strip:




Figure 3  
Mounting Vertical PDU

Figure 4  
Mounting Slimline Power Strip