

Troubleshooting Guide


for Bobrick B-828 SureFlo* Automatic, Top Fill Bulk Foam Soap Dispenser

ер	p 1: To determine cause: Unplug unit and reconnect unit look for Green LED light and sound of motor. Activate soap dispenser continually five times.				
	If motor running and LED does not light up consistently when hand is in the activation zone.				
	Likely Cause	Action	Instruction	Replacement Part/Kit Needed	
	Fiber Optic Nut may be thread too tight onto connector port in the Bottom Housing.	Check Fiber Optic Nut to see if nut has been overtightened	Tighten Fiber Optic Connector Nut hand tight and then rotate nut counterclockwise by 1/4 turn (90°).	n/a	
	No change.	All steps above completed.	Contact Bobrick Customer Service.	n/a	
	If motor running and LED lights up.				
	Likely Cause	Action	Instruction	Replacement Part/Kit Neede	
	Clogged Nozzle Tip.	Remove Nozzle Tip.	Clean with warm water and replace. Flush whole system. If Nozzle continutes to be clogged replace.	828-310	
	Soap may be too viscous.	Ensure that soap meets specified viscosity range. Viscosity less than 100cps (CPS = centerpoise) Adjust viscosity and Flush system.	Flush whole system. Replace with soap that is within recommended viscosity range.	n/a	
	No change.	All steps above completed.	Contact Bobrick Customer Service	n/a	
	If motor not running and LED lights up.				
	Likely Cause	Action	Instruction	Replacement Part/Kit Neede	
	Issue with Power Source this is determined by Flasing RED LED.	Check batteries. Check A/C adapter connection.	Replace with new batteries. Reconnect A/C adapter connection. If problem persists, send unit back to manufacturer.	n/a	
	Gear jamming.	Check for dried soap. Purge system.	Open Cover and pour warm water and then purge.	n/a	
	Flashing red LED. Indicates sensor obstruction.	Ensure all obstructions have been removed from sensor path.	Refer to mounting template.	824-307	
	No change.	All steps above completed.	Contact Bobrick Customer Service	n/a	
	If motor not running No LED light.				
	Likely Cause	Action	Instruction	Replacement Part/Kit Neede	
	No power to the unit	Replace with new batteries. Check A/C adapter connection.	If problem persists, send unit back to manufacturer.	n/a	
	No change.	All steps above completed.	Contact Bobrick Customer Service	n/a	
	Likely Cause	Action	Instruction	Replacement Part/Kit Neede	
1	Loose Stem connection to Bottle Cap.	Unscrew Stem Locking Nut.	Push the Bottle Assembly up onto the Stem until it stops. While pushing upwards on the Bottle, thread the Stem Locking Nut down onto the Bottle Cap threads. Reference Instruction Sheet 828-391.	n/a	
	Leaking from bottom of Bottom Housing.	Locate leak if from bottom of Bottom Housing.	Unit needs to be returned. Replace with Bottom Housing Replacment Kit.	828-550	
	Likely Cause	Action	Instruction	Replacement Part/Kit Neede	
	Foam Soap too Airy.	Adjust portion control knob. Also check Nozzle Tip Mesh Screen.	Turn knob clockwise for less air in foam. Clean Mesh Screen and / or replace.	828-310	
	Foam Soap too Liquidy/ Watery.	Adjust portion control knob. Also check Nozzle Tip Mesh Screen.	Turn knob counter clockwise. If Mesh Screen is torn replace.	828-310	

Parts List:

Item Description

- 1 Top Assembly with Spout, Door and Stem
- 2 LED Light Pipe
- 3 Foam Nozzle Tip with Mesh
- 4 Fiber Optic Insert with Sensor Lenses
- 5 Rubber Counter Gasket
- 6 Wave Washer
- 7 Mounting Nut
- 8 Stem Locking Nut
- 9 Foam Mixer Housing
- 10 Bottom Housing Assembly (includes Soap Bottle)
- 11 Optional: Battery Pack (requires (4) "D" cell alkaline batteries not included), order Part No. 824-241. For outlets not compatible with U.S. plugs, order Part No. 3974-58
- 12 (3) Fiber Optic Cables for Sensor and LED Light Pipe
- 13 Fiber Optic Connector Tip Assembly
- 14 Fiber Optic Nut
- 15 Portion Control Knob
- 16 Automatic System Flush Button
- 17 Key Hole
- 18 BobKey
- 19 Air Tube Adapter
- 20 Air Tube
- 21 A/C Adapter Kit with U.S. Plug For outlets not compatible with U.S. plugs, order Part No. 3974-58





Replacement Parts List			
Description			
A/C Adapter	3974-57		
International AC Adapter Plug Kit (U. K., Europe, Australia)	3974-58		
Mack Gasket Kit (To secure Top Assembly under the counter due to irregular counter surface)	824-167		
External A/C Multi Adapter Kit	824-201		
Nozzle Tip Replacement Kit Foam	828-310		
D Size Battery Pack (Batteries not included)	824-241		
Installation Hardware Packet with Foam Mixer Housing (Includes Wave Washer, Counter Gasket, Mounting Nut, BobKey, Stem Locking Nut)	828-443		
Top Housing Assembly Foam (Includes Installation Hardware Packet and Foam Mixer Housing)	828-525		
Bottom Housing Assembly Foam	828-550		

Recommended Foam Soaps			
Kutol Foaming Luxury Hand Soap			
Kutol Foaming Antibacterial Handsoap			
Chemcor Foaming Antibacterial Handsoap			
State Chemical Gentle Fresh Foaming Hand Soap			
State Chemical Gentle Fresh Defense Foaming Antibacterial Hand Soap			
SCJ Professional - Refresh Azure Foam			
Hillyard Cucumber-Melon, Premium Foam Soap			
Hillyard Green Select, Foaming Hand Soap			
Total Solutions, Green Apple Foam Soap			
Novo Antibacterial Foaming Hand Soap, Lemon Scented			
Spartan Lite'n Foamy, Citrus Fresh			
Germ-X Antibacterial Foaming Hand Wash			
Germ-X Green Foaming Hand Soap			
Betco Pink Foaming Skin Cleanser			
BETCO Green Earth Clear Foaming Skin Cleanser			
Enviro-Chem Foam Care Hand Soap			
DAYCON Foaming Hand Soap			
Recommended soaps are for reference only and do not constitute an endorsement of named manufacturer(s). All registrations and trademarks are the sole property of manufacturer.			



In the U.S.A.: BOBRICK WASHROOM EQUIPMENT, INC. 200 Commerce Drive, Clifton Park, New York 12065-1350 • Tel: (518) 877-7444 • Fax: 518-877-5029 6901 Tujunga Ave.,, North Hollywood, California 91605-6213 • Tel: (818) 982-9600 • Fax: 818-503-1102 or email customerservice@bobrick.com