


Disassembly Instructions

Connection Zone Benching

Material Type: A. Steel B. Wood C. Plastic



Procedure:

1. Remove the screws holding the worksurface to the leg assembly.
2. Remove the screws holding the hat channels to the leg weldments.
3. Remove the support beam from the leg weldments. A rubber mallet may be needed to strike the beam from below to loosen the hooks from the slots.
4. Remove the screw holding the angled support bracket to the beam.
5. Remove the glides from the bottom of the legs.

General Notes:

1. Disassembly time: 25-35 minutes
2. This procedure assumes basic familiarity with hand tools and furniture terminology: no specialized training is required
3. All materials removed and disassembled shall be sorted and segregated with like materials and disposed of or recycled according to recycling availability or waste acceptance
4. For items to be recycled, refer to KI's End of Life Recycling Matrix and KI's End of Life Recovery Options Matrix, available at www.ki.com

All fasteners not explicitly tagged or shown are Material Type A: Steel


Required Tools




Gloves




Safety Glasses



Philips Screwdriver



Rubber Mallet



Allen Wrench