





NOTE:


- Weight capacity is 200 lbs per leg.

2




Secure part with (4) mounting screws. (Note: Use appropriate screws and screw length depending on the table type and thickness.)

1



Determine the position and location of the part on under the work surface. Allow 1/2" clearance from the edge of the work surface.

3



Adjust glide leveler as needed.