

WG4/SET

PROPRIETARY AND CONFIDENTIAL.

ALL DIMENSIONS HAVE A $\pm 1/32"$ TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.


SPECIFICATIONS

- Maximum cord diameter is $3/8"$.


TABLE OF CONTENTS



..... 1X WG4 Lid




..... 1X WG4 Liner



TOP VIEW


FRONT VIEW

1



Make a cut out in the desired location on your work surface.
Cut a hole at 80.00mm ($3-5/32"$) diameter.

2




Install the WG4 Liner into the cutout and make sure it is fully leveled onto the work surface.

WG4/SET

PROPRIETARY AND CONFIDENTIAL.

ALL DIMENSIONS HAVE A $\pm 1/32$ " TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

3



Insert WG4 Lid into the WG4 Liner.