


SPHERA TR 37


L E U C O S[®]

INSTALLATION INSTRUCTIONS - LEUCOS USA

SPHERA T 20 - SPHERA T 29 SPHERA TR 37



SPHERA T 20



SPHERA T 29

A1

Enclosed



One installer



Save instructions

Revised

29 July 2008


WARNING: - DISCONNECT POWER BEFORE INSTALLATION.

- FIXTURE TO BE INSTALLED BY A CERTIFIED ELECTRICIAN. INSTALL IN ACCORDANCE WITH THE NATIONAL AND LOCAL ELECTRICAL CODES.
- TAKE GREAT CARE TO AVOID SCRATCHING OR CHIPPING THE GLASS WHEN CARRYING OUT THE OPERATIONS BELOW


ATTENTION IN CASE OF DAMAGE OF THE FLEXIBLE SUPPLY CABLE, SUBSTITUTION SHOULD BE CARRIED OUT BY THE CONSTRUCTOR, CLIENT SERVICE OR QUALIFIED PERSONNEL, IN ORDER TO AVOID DANGER.

1. **Fig.1**, Unscrew almost totally one of the two screws "X" and unscrew remove the second one.
2. **Fig.2**, Insert collar "B" inside the top opening, as show in **Fig.2** , and place the upper chrome polished part "A" on the opening collar of the diffuser. Then replace collar "B", from the below, through the threaded body of part "A". Take care to pull it up by keeping the still connected screw as shown in **Fig.3**.
3. **Fig.3**, Replace the removed screw and tighten it to the below collar "B" while tightening also the other one. Take care to couple firmly the two components "A" e "B". **Do not tighten** too much with the screwdriver in order to avoid scratching.
4. Insert bulb into lampholder and make a working test.
5. Place the diffuser over the threaded top of the base, as shown in **Fig.4** , and tighten carefully the diffuser till the complete locking.

FOR USA MARKET ONLY :

SPHERA T20 max 1x60 W 120V **E12** Type G16 ½ candelabre (Olive) 

SPHERA T29 max 1x100 W 120V **E26** Type A19 (White) 

SPHERA TR37 max 1x100 W 120V **E26** Type A19 (White) 

For additional information please contact your local dealer
or **LEUCOS U.S.A.** at: Tel. (732) 225-0010 Fax. (732) 225-0250

Fig.1




Fig.2




Fig.3




Fig.4

