PEC INSTALLATION AND ASSEMBLY INSTRUCTIONS

CAUTION: Risk of shock. Disconnect power before installing or servicing.

WARNING: Before proceeding, read all instructions carefully to insure proper and safe installation.

WARNING: Risk of electrical shock. High temperatures inside luminaire. Make certain line voltage corresponds with ballast/driver primary voltage (see ballast/driver label).

WARNING: All wiring to be performed per National Electrical Code and local code by a qualified electrician.

IMPORTANT: Not every unit is identical. Placement of proper luminaire is important. Refer to layout drawing to verify location identification, product location, and feed points.

IMPORTANT: Do not electrically connect to live wiring.

IMPORTANT: When relamping, always wear eye protection. Make sure area below luminaire is clear.

NOTE: If lamp is installed dirty, operating hours and performance will significantly decrease.




Installation Questions?
Call LSI Field Service Department at:
1-800-436-7800 Ext. 3300 Fax 877-861-1368

LSI Industries Inc. ◆ 10000 Alliance Road ◆ Cincinnati, OH 45242 ◆ 513-793-3200 ◆ Fax (513) 793-0147 ◆ www.lsi-industries.com

Page 1 of 2 583844

PEC INSTALLATION AND ASSEMBLY INSTRUCTIONS





Installation Questions?
Call LSI Field Service Department at:
1-800-436-7800 Ext. 3300 Fax 877-861-1368

LSI industries inc . • 10000 Alliance Road • Cincinnati, OH 45242 • 513-793-3200 • Fax (513) 793-0147 • www.lsi-industries.com

Page 2 of 2 583844