

INSTALLATION INSTRUCTIONS FOR 501, 502, 503, 504, 507, 510.

WARNING:

WIRING AND INSTALLATION MUST BE PERFORMED BY A QUALIFIED ELECTRICIAN ONLY.

TURN POWER OFF BEFORE INITIAL INSTALLATION, SERVICING, MAINTENANCE, OR RELAMPING. FOR USE WITH MAXIMUM 25A, 15V POWER UNITS ONLY.

FIXTURES SHOULD ALWAYS BE INSTALLED IN ACCORDANCE WITH LOCAL AND NATIONAL ELECTRIC CODES.

NOTE:

THIS IS A 12 VOLT FIXTURE. A REMOTE TRANSFORMER IS REQUIRED (NOT INCLUDED).

DO NOT INSTALL THIS FIXTURE IN ANY COMBUSTIBLE MATERIALS! USE UL LISTED WATERPROOF WIRE CONNECTORS: CAT, NUMBER KING-T6, MANUFACTURED BY KING TECHNOLOGY, INC OR EQUIVALENT.

INSTALLATION:

- 1. ASSEMBLE SPIKE AND FIXTURE BASE TOGETHER.

- 2. REMOVE FIXTURE STEM (IF ASSEMBLED). INSTALL LAMP.
 3. RETURN STEM TO BASE, MAKE SURE O-RING IS IN PLACE.
 4. POSITION FIXTURE IN ITS LOCATION. CHECK FIXTURE IS PLUMB.
- 5. CONNECT FIXTURE WIRES TO 12V POWER LINE FROM REMOTE TRANSFORMER (NOT INCLUDED).
 6. APPLY POWER TO FIXTURE TO TEST FOR PROPER OPERATION.

RELAMPING:

WARNING:

USE 12 VOLT 20 WATT (MAXIMUM) MR16 HALOGEN LAMP. CHECK PACKAGE AND FIXTURE LABELING CAREFULLY TO ENSURE USING LAMP OF PROPER TYPE AND WATTAGE.

TO RELAMP:

REMOVE (UNSCREW) FIXTURE STEM FROM BASE, PULL (DO NOT TWIST) THE LAMP OUT, PUSH A NEW LAMP IN, RETURN STEM TO BASE. CHECK O-RING. REPLACE IF NECESSARY.


> Cooper Lighting - Lumiere reserves the right to make design changes without notice.

ACRYLIC LENSES AVAILABLE WITH LUMIERE MINI BOLLARDS: (LENSES ARE FACTORY INSTALLED AND ARE NOT FIELD REPLACEABLE)











Α	02-27-02	PRODUCTION RELEASE				ğ	
ĕ	DATE	DES	ESCRIPTION			2142	
INSTALLATION INSTRUCTIONS			٧	Lumfère empre lapas. 1260 Cele Bueta Garantia, DA 93011. Telapare: (823) 445-7713 FAV. (856) 445-7612			
MODEL 501,502,503,504,507,510			DWG No.	вис њ. 8794		⊅₫	
DITSWN ELENA KUSHINSKAYA				BHEET 1 OF 1			