


Parts Diagram

Strive® Nesting Chair

Poly and Upholstered Seat Armless Chair

August 2019



.XX = Select Color

COR = Custom Option Request

Item	Part Number	Item Description	Req Qty	Item	Part Number	Item Description	Req Qty
1	COR	Pressure Fit Back, Armless Frame	1	10	46.5381.L.XX.X	Cover, No-Arm Frame, LH	1
2	46.5367.XX.X	Board, Seat	1	11	12.0266	Spring Pin, 1/4 x 1 1/2	1
3	42.0100	Mounting Plate, Seat Shroud	2	12	12.0032.X	Tinnerman Clips	2
4	46.5068.X	Clip, Cylindrical	6	13	46.5369.XX.X	Cap, Tube End	2
5	46.5365.XX.X	Shroud, Seat	1	14	46.0385.XX.X	Cap, Tube End	2
6	SNRC	Upholstered Seat	1	15	46.5417.BL.X	Bushing, 1" OD Tube Caster	4
7	46.5366.XX	Cover, Seat Mounting	1	16	09.0440.BL.X	Caster, 60mm Diameter Carpet	4
8	12.0228	Screw, 1/4-20 x 2 PPH MS ZC	4		09.0441.BL.X	Caster, 60mm Diameter Hard Floor	4
9	46.5381.R.XX.X	Cover, No-Arm Frame, RH	1	17	10.0150.X	Glide, Bell	4