




NOTE:

- Maximum cord diameter is  $1/2"$ .
- Part is handmade and slight variations in textures and color may occur.
- All dimensions have a  $\pm 1/16"$  tolerance. We do not recommend drilling or cutting any holes before receiving a product or a product sample.




FRONT VIEW

1



Determine the position and location of the part in the work surface. Make a  $1-3/4"$  diameter cut out.

2



Install the WG2 into the cut out. Make sure part is fully leveled on the work surface.