



Lakeland #R3035

## Product Specification

Face Construction	Imperial	Metric
Construction	Level Cut Loop	
Tufted Pile Weight	26 oz/sq yd	881 g/sq m
Twist Level	4.91 TPI	
Gauge	1/10 inch	39.4 rows/10 cm
Stitches per Inch	9 stitches / inch	35.4 stitches/10 cm
Pile Height	0.312 inch Cut	7.9 mm
	0.250 inch Loop	6.4 mm
Total Weight	62.0 oz/sq yd	2102 g/sq m
Pile Density	3000	
Fiber System	100% Solution-dyed Primus® PET Fiber	
Dye Method	Solution Dyed	
Pattern Repeat	2" W x 2.75" L	50 mm W x 70 mm L
Primary Backing	Woven Polypropylene	
Backing Construction	Actionbac®	
Width	12 feet	366 cm

### Product Testing/Information

Surface Flammability	Flooring Radiant Panel	ASTM E-648 Class 1
	Smoke Density	ASTM E-662 Less than 450

The product, represented by averages of testing from random samplings of production lots, meets or exceeds the above Test Results.

### Installation and Maintenance

Carpet should be installed in accordance with the Carpet and Rug Institute's standard CRI-104. Carpet must be over manufacturer's recommended pad.

Stretch-In Installation: Establish roll sequencing, dry lay carpet, and apply latex seam sealer to both edges. Pre-stretch the sections with shorter pattern measurements to align with longer patterns in order to make hot melt seam (use 6" tape to prevent seam peaking).

A two-headed power stretcher or "deadman" must be used to achieve this. Once the seam is made, proceed with proper stretch installation (CRI-104, figure "Stretch Diagram"). The use of architectural or double tackless strip is required to be used throughout a stretch-in installation.

Pattern streaks and banding are visually apparent streaking in patterned carpet resulting from linear juxtaposition of pattern elements visible in both length and width direction. IT IS NOT A CARPET DEFECT, but is inherent in solution dyed graphic and cut/loop patterns.

### Warranties

- Limited 10 Year Abrasive Wear Warranty
- Limited 10 Year Manufacturing Warranty

### Product Notes

- All specifications are subject to normal manufacturing tolerances.
- Dyelots may vary from samples.
- The use of chair pads under roller caster chairs is required in order to maintain full limited warranty coverage.
- Tarkett reserves the right to change specifications and construction materials without notice due to raw material shortages or technological improvements, contact your representative for confirmation.

### Tarkett North America

Technical Services Department  
285 Kraft Drive  
Dalton, GA 30721  
USA: 800-871-3211

[www.tarkettna.com](http://www.tarkettna.com)

© 2022 Tarkett USA Inc. 10/2022