



Pinecrest #R8100

Product Specification

Face Construction	Imperial	Metric
Construction	Textured Loop	
Tufted Pile Weight	26 oz/sq yd	881 g/sq m
Twist Level	4.91 TPI	
Gauge	1/10 inch	39.4 rows/10 cm
Stitches per Inch	10 stitches / inch	39.4 stitches/10 cm
Pile Height	0.250 inch Medium	6.4 mm
	0.125 inch Low	3.2 mm
Total Weight	62.0 oz/sq yd	2102 g/sq m
Pile Density	4193	
Fiber System	100% Solution-dyed Primus® PET Fiber	
Dye Method	Solution Dyed	
Pattern Repeat	0.6" W x 0.75" L	15 mm W x 19 mm L
Primary Backing	Woven Polypropylene	
Backing Construction	Actionbac®	
Width	12 feet	366 cm

Product Testing/Information

Surface Flammability	Flooring Radiant Panel	ASTM E-648 Class 1
	Smoke Density	ASTM E-662 Less than 450

The product, represented by averages of testing from random samplings of production lots, meets or exceeds the above Test Results.

Installation and Maintenance

Carpet should be installed in accordance with the Carpet and Rug Institute's standard CRI-104. Carpet must be over manufacturer's recommended pad.

Stretch-In Installation: Establish roll sequencing, dry lay carpet, and apply latex seam sealer to both edges. Pre-stretch the sections with shorter pattern measurements to align with longer patterns in order to make hot melt seam (use 6" tape to prevent seam peaking).

A two-headed power stretcher or "deadman" must be used to achieve this. Once the seam is made, proceed with proper stretch installation (CRI-104, figure "Stretch Diagram"). The use of architectural or double tackless strip is required to be used throughout a stretch-in installation.

Pattern streaks and banding are visually apparent streaking in patterned carpet resulting from linear juxtaposition of pattern elements visible in both length and width direction. IT IS NOT A CARPET DEFECT, but is inherent in solution dyed graphic and cut/loop patterns.

Warranties

- Limited 10 Year Abrasive Wear Warranty
- Limited 10 Year Manufacturing Warranty

Product Notes

- All specifications are subject to normal manufacturing tolerances.
- Dyelots may vary from samples.
- The use of chair pads under roller caster chairs is required in order to maintain full limited warranty coverage.
- Tarkett reserves the right to change specifications and construction materials without notice due to raw material shortages or technological improvements, contact your representative for confirmation.

Tarkett North America

Technical Services Department
285 Kraft Drive
Dalton, GA 30721
USA: 800-871-3211

www.tarkettna.com

© 2022 Tarkett USA Inc. 10/2022