

KEILHAUER

Epix Shelf

Assembly Instructions, Models 76111, 76112 & 76113


Tool Required

Phillips head screw driver




Hardware Included


1/4-20 x 3/4"
Flat head cap screw
(x52)




Place each column sub assembly (x3) on its side on a blanket approximately 28 inches apart. The center column does not have a bottom support mount.




Using the Phillips head screw driver, fasten the column sub assembly (x3) to the bottom shelf platform with 1/4-20 x 3/4" flat head cap screw (x12).




Using the Phillips head screw driver, fasten the two bottom end supports using 1/4-20 x 3/4" flat head cap screw (x4).



Turn the shelf into the upright position. Slide the remaining shelf platforms through the uprights in to position.



Using the Phillips head screw driver, fasten the remaining shelf platforms with 1/4-20 x 3/4" flat head cap screw (x36).



Place assembled shelf in its final position.