







Apply adhesive or double-sided tape to the back of the WM2A. If purchased with double-sided tape pre-installed, proceed to step 2.



Determine the position and location on the work surface in which to apply the WM2A. The WM2A can be mounted underneath or on the side of the work surface.




Apply pressure to the WM2A when placing against the work surface until it is held into position by the adhesive.



Place wires into position by slipping them through the small opening on top of the WM2A.

TABLE OF CONTENTS:



..... WM2A