

METAL CEILINGS & WALLS

Cleaning Instructions

METAL PANEL MAINTENANCE:

- Painted ceiling panels should be wiped down as necessary with a non-rinsing cleaner such as tri-sodium phosphate (T.S.P.) or equal.
- Stubborn stains and grease marks can be removed with cleaners such as Formula 409 or Fantastic.
- Use only lint free, soft cloths for wiping down.
- Avoid the use of abrasive cleaners such as Comet or Ajax.
- The Bright and Brushed Finishes should be cleaned with glass cleaners such as Windex, Glass Plus, etc. Wipe in direction of the panel only. Do not use circular motions. Use only soft, lint free cloths.

CertainTeed Ceilings Corporation 20 Moores Road, Malvern, PA 19355 U.S.A.

TM ® CertainTeed is a trademark of CertainTeed LLC
All other trademarks are the property of
CertainTeed Ceilings Corporation or its affiliates.