


Atrio 34 088

Exposed Thermostatic Shower Valve

Exploded View



Parts Breakdown

Pos. No.	Spare part Description	Product No.	Pcs.
	34088 / 34089		
1	Trio handle	47680	1
1.1	Insulator	08943	1
1.2	Set screw	11232	1
2	Lever handle	47682	1
2.1	Insulator	08943	1
2.2	Set screw	11232	1
3	Temperature handle	07627	1
4	Therm. cartridge w/ non rising	47682	1
4.1	Therm. cartridge only	47302	1
4.1.1	O-rings	01218	1
4.1.2	O-rings	05999	1
4.1.3	O-rings	01196	1
4.2	Nonrising cap	47300	1
4.2.1	Clip	05744	1
5	Seat	08328	1
6	Volume control insulator	47311	1
6.1	O-ring	03540	1
7	Volume control cartridge	45346	1
7.1	O-ring	03924	1
8	Union complete	47681	1
8.1	Washer	08297	1
8.2	Screen	07264	1
8.3	Union sleeve/escutcheon	47638	1
9	vacum breaker	07911	1
	Special accessories		
10	Reverse cartridge	47282	1